Q



KZN Health Intranet KZN HEALTH


Search this site

CORPORATE INFORMATION COMPONENTS DIRECTORY DISTRICT OFFICES

KZN Health > Components > Supply Chain Management

HOME

AdvertQuote



Mrs G. Anderson

No late quotes will be considered

Finance Manager Name:

Finance Manager Signature:



Qu	ote Number:
Ite	m Description: Restore functionality to AC split units in HR top floor (NSI 001 A MNT 21.22 01.04.2021)
De	partment/Section: Human Resource Department Purpose of Item: Repairing of AC split units
1.	Pre-qualification criteria if any:
	1.1. Is the works required to have a regulatory body certification (e.g. SABS, SANS, SANAS, ISO, CIDB, etc.)? Yes: 1.1. Is the works required to have a regulatory body certification (e.g. SABS, SANS, SANAS, ISO, CIDB, etc.)? Yes: 1.1. Is the works required to have a regulatory body certification (e.g. SABS, SANS, SANAS, ISO, CIDB, etc.)? Yes: 1.1. Is the works required to have a regulatory body certification (e.g. SABS, SANS, SANAS, ISO, CIDB, etc.)? Yes: 1.1. Is the works required to have a regulatory body certification (e.g. SABS, SANS, SANAS, ISO, CIDB, etc.)? Yes: 1.1. Is a compulsory site inspection / briefing session required? Yes / No
	if Yes, specify: Date/ Time: Place
	1.3. Is local production and content part of the quote? Yes / No
	if Yes, specify:
	1.4. Provisions of section 4(1) (a) of the PPPFA Regulations, 2017 if applicable? Yes
	if Yes, specify:
	1.5. Liability Cover insurance? Yes / No
	if Yes, specify: <u>Yes; 3rd party liability cover/insurance</u>

2. What is the specification of the required item?

List sp	ecifications to be advertised	Comment
1.	Advertising stage	
1.1	Should it be found by any contractor wanting to tender for the below works, that there are any discrepancy or any unclearness of the advertised tender document, the advertiser (SCM 031 360 3446/3465) should be notified prior attending the site meeting. Note: If any tenderer arrives on site and it is discovered that the tender document is not complete or not clear, the site meeting will be cansled.	
1.2	Only companies that have refrigeration installation and maintance in their core business will be accepted for quotations.	
1.3	Strictly – No sub-contracting of any part of the works will be allowed unless it is accompanied with strong motivation and supporting documentation on company letterhead and attached to tender Specialist services (Sub – contracting) and their pricing must not exceeding 15% of the total primary contractor pricing/Quotation.	
2.	Site meeting requirements:	
2.1	Site meeting Safety	
2.1.1	All tenderers attending site meeting must have hard tipped safety shoes and face masks	
2.2	Attending site meeting	
2.2.1	Please note: The person attending the site meeting will be classified (By the institution Project leader) as the Company project leader, and all matters arising prior submitting quotes and after the site meeting and during works will be only directed to that person that attended the site meeting to avoid confusion later in the project duration. It is therefore strongly recommended to send the correct person/s to represent your Company to attend the site meeting. No other person/s will be entertained	
2.3	Site meeting tools: Measuring tape, note book and Pen.	
	Note: No alterations will be allowed to the tender works specifications	
	to be quoted on, unless all involved parties agree to it. Should any amendment be made, (All companies will sign each	

Name of End-user (in full)	Name of SCM Rep (in full)	
Designation / Rank (in full)	Designation/ Rank (in full)	
Signature	Signature	
Date	Date	



	other's document/s) the relevant institution project leader will draft the		
	amendment and sought the approval on Maintenance Manager and		
	once approved it will be send to all companies that had tender		
	documents on site the same day.		
2.4	Site meeting will be held at 11H00 sharp of which the date will be on the advert.		
2.5	Tenderers are reminded to print the entire tender document and bring it to the site meeting. Note: Any tenderer coming to site without tender document will be		
	disqualified		
2.6	This tender works will only allow one artisan (that will attend the work) and one unskilled person (that holds the step ladder for the artisan) that has been trained in the safe use of step ladders.		
3.	Pre-qualification evaluation criteria	Evaluation points	Comments
1	4	%	
3.1	CIDS ME3 company registration in Air conditioning Installation and maintenance (Must be core business of the company)	5	
3.2	Certified copy of SARACCA registered person (Class A4) that will be carrying out the work/s to be attached to tender document.(Front and back copy).	5	
3.3	Refrigeration artisan Qualification trade test certificate (SARACCA A4 or higher SARACCA classification)	5	
3.4	Artisan 1 - 2 year = 1 point, 3 - 4 year = 3 points, 5 year and above = 5 points Experience(after trade test) (Company Human Resource department certification required)	5	
3.5	Compile complete bill of material (This is to be done per AC split unit on BOQ) Quote for all material needed to complete the works on quote form attached to tender. (Example: Tender required installation of split unit compressor – Quote do not reflect Nitrogen gas, gas welding gas, welding rods (copper tac or compression fittings to install compressor) [will result in 0 points and disqualification of tender]. Failure to complete the BOQ and in prescribed manner, will result in tender disqualification.	70	
3.6	Submit execution plan of each consecutive day of what work will be	5	
	done and in which area.		
3.7	Previous work record references (with dated company stamps and signed by relevant reference company) for the last 5 years.	5	
	Total		
4.1	Prior planed arrival an email notification shall be send to <u>Eugene.Allerston@kznhealth.gov.za</u> before arrival on site to make security aware of you and your staff's expected presence.		
	List of all persons and their designations to be attached on the email. Note: While on the premises, no person shall be allowed to enter or go to any other department which is not listed on the work plan at any given time, other than the casualty department for injury on duty purposes and Tuck shop or Kitchen for the purpose of food.		
4.2	All staff entering the premises shall have visible on their person, Company ID cards with full names, ID no and Photo		
5.	Manner in which works is to be attended		
5.1	Submitting of safety file with safety officer. (In Maintenance		
	department first floor)		
5.2	Once safety file has been approved and email confirmation has been received from safety officer to relevant Maintenance project leader, the		



hand over meeting to confirm that the contractor is fully aware of what is expected from him/her in executing the works. – In this time, meeting minutes will be taken and signed by both the Company project leader (Site meeting attendee) and Institution project leader and emailed to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader office can be signed and works can start. 4. Works required. 4. Admin HR top floor back office left – Room 34 18000 btu carrier 5. Admin HR top floor back office left – Room 34 18000 btu carrier 6. Admin HR top floor back office right – Room 34 18000 btu carrier 7. Admin HR top floor back office right – Room 34 18000 btu carrier 8. Admin HR top floor back office right – Room 34 18000 btu carrier 8. Admin HR top floor back first right front back— Room 34 18000 btu carrier 9. Admin HR top floor back first right front back— Room 34 18000 btu carrier 9. Admin HR top floor back first right front back— Room 34 18000 btu carrier 9. Admin HR top floor back first right front back— Room 34 18000 btu carrier 9. Admin HR top floor back first left front— Room 34 18000 btu carrier 1. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 2. Admin HR top floor back first left front— Room 34 18000 btu carrier 8. Admin HR top floor back first left front— Room 34 18000 btu carrier 9. Admin top floor Room 35 18000 btu carrier 1. Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 1. Admin top floor Room 35 18000 btu carrier 1. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 2. Admin to		The following documents will be required to open the file:	
tender) - Contractor 2. Official works order - Contractor 3. Full and comprehensive work plan/execution plan - with concurrent dates and description of work that will be executed Contractor. 3. Immediately following the file opening, there will be a pre briefing site hand over meeting to confirm that the contractor is fully aware of what is expected from him/her in executing the works In this time, meeting minutes will be taken and signed by both the Company project leader (site meeting attendee) and Institution project leader and emailed to the company Director (for signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director (for signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director (for signing and acknowledgement) prior starting any works. 4. Works required. 4. Works required. 5. Admin HR lop tition back office left - Room 34 18000 bits carrier of the plant of the prior of the plant of the plan			
2. Official works order - Contractor 3. Full and comprehensive work plant/execution plan - with concurrent dates and description of work that will be executed. — Contractor. 3. Immediately following the file opening, there will be a pre briefing site hand over meeting to confirm that the contractor is fully aware of what is expected from him/her in executing the works. — In this time, meeting minutes will be taken and signed by both the Company project leader (Site meeting attendee) and Institution project leader and emailed to the company Director (For signing and acknowledgment) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader, the onsite company attendance register at institution project leader office can be signed and works can start. 4. Works required. 4. Works required. 5. Works required. 6. Admin HR top floor back office left — Room 34 18000 btu carrier 7. Replace compressor capacitor, Compressor direr, flush unit and oharge with refrigerant gas and clean and distinct indoor unit completely. 8. Admin HR top floor back office right — Room 34 18000 btu carrier 9. Admin HR top floor back office right — Room 34 18000 btu carrier 1. Replace compressor capacitor, Compressor direr, flush unit and charge with refrigerant gas and clean and distinct indoor unit completely. 9. Admin HR top floor back first right front back— Room 34 18000 btu carrier 1. Replace compressors capacitor, Compressor direr, flush unit and charge with refrigerant gas and clean and distinct of unit completely. 1. Admin the floop floor back first left, front— Room 34 18000 btu carrier 1. Replace compressor capacitor, compressor, direr, flush unit and charge with refrigerant gas and clean and distincted entire unit completely. 1. Admin top floor Room 35 18000 btu carrier 1. Replace compressor capacitor, compressor, direr, flush unit and charge with gas		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
3. Full and comprehensive work plan/execution plan—with concurrent dates and description of work that will be executed. - Contractor. Immediately following the file opening, there will be a pre briefling site hand over meeting to confirm that the contractor is fully aware of what is expected from him/her in executing the works.—In this time, meeting minutes will be taken and signed by both the Company project leader (site meeting attendee) and Institution project leader and emailed to the company Director (For signing and acknowledgement) prior starting any works. Once the minutes is signed and acknowledged and signed by the company Director (For signing and acknowledgement) prior starting any works. Once the minutes is signed and acknowledged and signed by the company Director (For signing and acknowledgement) prior starting any works. Works required. Works required. Admin HR log floor back office left – Room 34 18000 bu carrier Replace compressor capacitor, Compressor dier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR log floor back office right – Room 34 18000 bu carrier Replace compressor capacitor, Compressor dier, flush unit and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. Admin HR log floor back office right – Room 34 18000 bu carrier Admin HR log floor back first right front back – Room 34 18000 btu carrier Admin HR log floor back first right front back – Room 34 18000 btu carrier Admin the log floor back first right front back – Room 34 18000 btu carrier Admin to floor floor minute of the starting of the prior back – Room 34 18000 btu carrier Admin to floor floor minute of the starting of the star			1
concurrent dates and description of work that will be executed. — Contractor. — Contractor. Immediately following the file opening, there will be a pre briefing site hand over meeting to coriffirm that the contractor is fully aware of what is expected from him/her in executing the works. — In this time, meeting minutes will be taken and signed by both the Company project leader (Site meeting attendee) and Institution project leader and emailed to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader of life or an be signed and works can start. 4. Works required. 4. Works required. 5. Works required. 6. Admin HR top floor back office left — Room 34 18000 btu carrier and charge with refrigerant gas and clean and disinfect indoor unit completely. 9. Admin HR top floor back office right — Room 34 18000 btu carrier and acknowledge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. 9. Admin HR top floor back office right — Room 34 18000 btu carrier fan and clean and disinfect indoor unit completely. 9. Admin HR top floor back first right front back.— Room 34 18000 btu carrier fan and clean and disinfect indoor unit completely. 9. Admin HR top floor back first right front back.— Room 34 18000 btu carrier fan and clean and disinfect indoor unit completely. 9. Admin HR top floor back first left front.— Room 34 18000 btu carrier fan and clean and disinfect indoor unit completely. 9. Admin HR top floor back first left front.— Room 34 18000 btu carrier fan fan displace unit in its entrety and issue Cot crifigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and peint work to the satisfaction of institution Project leader. 9. Admin top floor Room 37 18000 btu carrier fan Replace compressor capacitor, compressor, dier, flush unit and charge with gas and clean and disinfect			
- Contractor. 3 Immediately following the file opening, there will be a pre briefing site hand over meeting to confirm that the contractor is fully aware of what is expected from himher in executing the works. — In this time, meeting minutes will be taken and signed by both the Company project leader (site meeting attendee) and Institution project leader and emailed to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader, office can be signed and works can start. 4. Works required. 4. Admin HR log flior back office left — Room 34 18000 btu carrier 5. Admin HR log flior back office left — Room 34 18000 btu carrier 6. Replace compressor capacitor, Compressor direr, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 5. Admin HR log flior back office right — Room 34 18000 btu carrier 6. Admin HR log flior back iffice right Front back— Room 34 18000 btu carrier 7. Replace compressor capacitor, Compressor dier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 8. Admin HR log flior back lifer right Front back— Room 34 18000 btu carrier 8. Admin the log flior back lifer right front disturbed brick, plaster and plant work to the satisfaction of institution Project leader. 9. Admin to flior back lifer left front disturbed brick, plaster and plant work to the satisfaction of institution Project leader. 9. Admin to flior Room 37 18000 btu carrier 10. Admin to flior Room 37 18000 btu carrier 10. Admin to flior Room 37 18000 btu carrier 10. Admin to flior Room 38 Labour department Assistant 18000 btu carrier unit completely. 11. Admin to flior Room 40 18000 btu			
immediately following the file opening, there will be a pre briefing site hand over meeting to confirm that the contractor is fully aware of what is expected from him/her in executing the works. — In this time, meeting minutes will be taken and signed by both the Company project leader (Site meeting attendee) and Institution project leader and emailed to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader of the onsite company attendance register at institution project leader office can be signed and works can start. 4. Works required. 4. Works required. 5. Admin HR too floor back office left — Room 34 18000 btu carrier. 6. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 6. Admin HR too floor back office right — Room 34 18000 btu carrier. 7. Replace all clean and disinfect indoor unit completely. 8. Admin HR too floor back first right front back—Room 34 18000 btu carrier. 9. Admin HR too floor back first right front back—Room 34 18000 btu carrier. 9. Admin HR too floor back first right front back—Room 34 18000 btu carrier. 9. Admin HR too floor back first left front—Room 34 18000 btu carrier. 9. Admin HR floor back first left front—Room 34 18000 btu carrier. 10. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 11. Replace unit in its entirely and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 12. Admin HR floor Room 35 18000 btu carrier. 13. Replace compressor capacitor, compressor, dier, flush unit and charge with gas and clean and disinfect entire unit completely. 14. Admin Hop floor Room 37 18000 btu carrier. 15. Admin top floor R	H	concurrent dates and description of work that will be executed.	
hand over meeting to confirm that the contractor is fully aware of what is expected from him/her in executing the works. – In this time, meeting minutes will be taken and signed by both the Company project leader (Site meeting attendee) and institution project leader and emailed to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader, office are the signed and works can start. 5. Admin HR top floor back office left – Room 34 18000 btu carrier. 6. Admin HR top floor back office left – Room 34 18000 btu carrier. 7. Replace compressor capacitor, Compressor drier, flush unit and charge with refigerant gas and clean and disinfect indoor unit completely. 8. Admin HR top floor back office right – Room 34 18000 btu carrier. 8. Admin HR top floor back office right – Room 34 18000 btu carrier. 9. Admin HR top floor back office right – Room 34 18000 btu carrier. 10. Admin HR top floor back office right – Room 34 18000 btu carrier. 11. Replace compressor capacitor, Compressor drier, flush unit and charge with refigerant and replace evaporator fan and clean and disinfect indoor unit completely. 12. Admin HR top floor back first right front back.—Room 34 18000 btu carrier. 13. Replace compressor capacitor, Compressor drier, flush unit and charge with refigerant gas and clean and disinfect indoor unit completely. 14. Admin HR top floor back first left front.—Room 34 18000 btu carrier. 15. Admin HR top floor back flist left front.—Room 34 18000 btu carrier. 16. Replace unit in its entirety and issue COC refigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the estilisation of institution project leader. 16. Admin top floor Room 37 18000 btu carrier. 17. Admin top floor Room 37 18000 btu carrier. 18. Replace parasonic wall mo			l
is expected from him/her in executing the works. — In this time, meeting minutes will be taken and signed by both the Company project leader (Site meeting attendee) and Institution project leader and emailed to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader office can be signed and works can start. 4. Works required. 5. Works required. 6. Admin HR top floor back office left — Room 34 18000 btu carrier. 7. Admin HR top floor back office left — Room 34 18000 btu carrier. 8. Admin HR top floor back office right — Room 34 18000 btu carrier. 9. Admin HR top floor back office right — Room 34 18000 btu carrier. 9. Admin HR top floor back office right — Room 34 18000 btu carrier. 1. Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. 3. Admin HR top floor back first right front back. Room 34 18000 btu carrier. 8. Admin HR top floor back first right front back. Room 34 18000 btu carrier. 9. Admin HR top floor back first right front back. Room 34 18000 btu carrier. 1. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 4. Admin HR top floor back first left front—Room 34 18000 btu carrier. 4. Admin HR top floor Room 35 18000 btu carrier. 5. Admin top floor Room 35 18000 btu carrier. 6. Admin top floor Room 37 18000 btu carrier. 6. Admin top floor Room 37 18000 btu carrier. 6. Admin top floor Room 37 18000 btu carrier. 6. Admin top floor Room 37 18000 btu carrier. 6. Admin top floor Room 37 18000 btu carrier. 6. Admin top floor Room 38 18000 btu carrier. 7. Admin top floor Room 40 18000 btu carrier. 8. Admin top floor Room 40 18000 btu carrier. 8. Admin top floor Room 40 18000 btu carrier. 8. Admin top floor pack	5.3		
meeting minutes will be taken and signed by both the Company project leader (Site meeting attendee) and Institution project leader and emalled to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader, the onsite company attendance register at institution project leader, office can be signed and works can start. 4. Works required. 4. Admin HR top floor back office left – Room 34 18000 btu carrier 5. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 4. Admin HR top floor back office right – Room 34 18000 btu carrier 5. Replace sompressor capacitor, Compressor drier, flush unit and clean and disinfect indoor unit completely. 4. Admin HR top floor back first right front back.—Room 34 18000 btu carrier 5. Admin HR top floor back first right front back.—Room 34 18000 btu carrier 6. Admin HR top floor back first right front back.—Room 34 18000 btu carrier 6. Admin HR top floor back first left. Iront—Room 34 18000 btu carrier 6. Admin HR top floor back first left. Iront—Room 34 18000 btu carrier 6. Admin the Roo floor back first left. Iront—Room 34 18000 btu carrier 6. Admin top floor Room 35 18000 btu carrier 6. Admin top floor Room 35 18000 btu carrier 6. Admin top floor Room 37 18000 btu carrier 6. Admin top floor Room 37 18000 btu carrier 6. Admin top floor Room 37 18000 btu carrier 6. Admin top floor Room 37 18000 btu carrier 6. Admin top floor Room 40 18000 btu Panasonic wall mount unit and charge with gas and clean and disinfect entire unit completely. 6. Admin top floor Room 60 18000 btu Panasonic wall mount unit satisfaction of institution project leader. 6. Admin top floor Room 60 18000 btu Panasonic wall mount unit satisfaction of institution project leader. 6. Admin top fl			
project leader (Site meeting attendee) and Institution project leader and emailed to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader office can be signed and works can start. 5. Works required. 6. Works required. 1. Admin HR top floor back office left — Room 34 18000 btu carrier. 1. Admin HR top floor back office left — Room 34 18000 btu carrier. 1. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 2. Admin HR top floor back office right — Room 34 18000 btu carrier. 2. Papelace and clean and disinfect indoor unit completely. 3. Admin HR top floor back first right front back—Room 34 18000 btu carrier. 3.1 Replace compressor capacitor, Compressor drier, flush unit and charge with retrigerant gas and clean and disinfect indoor unit completely. 4. Admin HR top floor back first left front—Room 34 18000 btu carrier. 5. Admin HR top floor back first left front—Room 34 18000 btu carrier. 6. Admin HR top floor back first left front—Room 34 18000 btu carrier. 7. Admin HR top floor back first left front—Room 34 18000 btu carrier. 8. Admin HR top floor Room 35 18000 btu carrier. 8. Admin top floor Room 35 18000 btu carrier. 8. Admin top floor Room 37 18000 btu carrier. 8. Admin top floor Room 37 18000 btu carrier. 8. Admin top floor Room 37 18000 btu carrier. 8. Admin top floor Room 37 18000 btu carrier. 8. Admin top floor Room 37 18000 btu carrier. 8. Admin top floor Room 37 18000 btu carrier. 8. Admin top floor Room 37 18000 btu carrier. 8. Admin top floor Room 40 18000 btu carrier. 8. Admin top floor Room 40 18000 btu carrier. 8. Admin top floor Room 40 18000 btu carrier. 8. Admin top floor Room 40 18000 btu carrier. 8. Admin top floor Room 57 18000 btu carrier. 8. Admin t		· -	
and smailled to the company Director (For signing and acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendence register at institution project leader office can be signed and works can start. 4. Works required. 4. Admin 18t top floor back office left - Room 34 18000 btu carrier 7. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 2. Admin 18t top floor back office right - Room 34 18000 btu carrier 2.1. Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. 3. Admin 18t top floor back first right front back. Room 34 18000 btu carrier 4. Admin 18t top floor back first right front back. Room 34 18000 btu carrier expects of the statistical control of institution Project leader. 5. Admin top floor Room 35 18000 btu carrier 5. Admin top floor Room 35 18000 btu carrier 6. Admin top floor Room 37 18000 btu carrier 6. Admin top floor Room 37 18000 btu carrier 7. Replace compressor capacitor, compressor, dier, flush unit and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor Room 37 18000 btu carrier 8. Admin top floor Room 37 18000 btu carrier 8. Admin top floor Room 37 18000 btu carrier 9. Admin top floor Room 37 18000 btu carrier 1. Replace and charge with gas and clean and disinfect entire unit completely. 1. Admin top floor Room 40 18000 btu Panasonic wall mount unit 1. Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed exposed Mack, plasts front for place and disinfect entire unit complet			
acknowledgement) prior starting any works. 4. Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader office can be signed and works can start. 4. Works required. 1.1. Admin HR top floor back office left – Room 34 18000 btu carrier 1.1. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 2. Admin HR top floor back office right – Room 34 18000 btu carrier 8. Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. 3.1. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 3.1. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 4. Admin HR top floor back first left front. Room 34 18000 btu carrier 8. Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and plant work to the satisfaction of institution Project leader. 5. Admin top floor Room 35 18000 btu carrier 8. Admin top floor Room 35 18000 btu carrier 8. Admin top floor Room 35 18000 btu carrier 8. Admin top floor Room 37 18000 btu carrier 9. Admin top floor Room 37 18000 btu carrier 1. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 1. Admin top floor Room 40 18000 btu carrier 1. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 2. Admin top floor Room 40 18000 btu carrier 3. Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed exposed Marchage leader. 3. Replace Repairs was an clean and disinfect entire unit completely. 3. Admin top			
Once the minutes is signed and acknowledged and signed by the company Director and emailed back to the Institution project leader office can be signed and works can start. Works required. Admin HR top floor back office left – Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back office left – Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back office right – Room 34 18000 btu carrier Replace and clean and disinfect indoor unit completely. Admin HR top floor back first right front back – Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front – Room 34 18000 btu carrier Admin HR top floor back first left front – Room 34 18000 btu carrier Admin HR top floor back first left front – Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Admin top floor Room 37 18000 btu carrier Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Makel, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 40 18000 btu carrier Admin top floor left Room 43 18000 btu carrier Admin top floor plast Room 43			
company Director and emailed back to the Institution project leader, the onsite company attendance register at institution project leader office can be signed and works can start. Works required. Admin HR top floor back office left — Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back office right — Room 34 18000 btu carrier Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. Admin HR top floor back first right front back—Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front—Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front—Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor com 43 18000 btu carrier Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Media, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top fl			
the ensite company attendance register at institution project leader office can be signed and works can start. Works required. Admin HR top floor back office left – Room 34 18000 btu carrier Admin HR top floor back office left – Room 34 18000 btu carrier Replace compressor capacitor, Compressor dier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back office right – Room 34 18000 btu carrier Repair gas leak and charge with refrigerant and replace evaporator lan and clean and disinfect indoor unit completely. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front– Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Admin top floor Room 37 18000 btu carrier Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Makel, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 43 18000 btu carrier Admin top floor left Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Admin t	5.4	T T T T T T T T T T T T T T T T T T T	
office can be signed and works can start. Works required. 1. Admin HR top floor back office left – Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 2. Admin HR top floor back office right – Room 34 18000 btu carrier Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. 3. Admin HR top floor back first right front back – Room 34 18000 btu carrier 3.1 Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 4. Admin HR top floor back first left front – Room 34 18000 btu carrier 5. Admin HR top floor back first left front – Room 34 18000 btu carrier 6. Admin HR top floor back first left front – Room 34 18000 btu carrier 7. Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 5. Admin top floor Room 35 18000 btu carrier 6. Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. 6. Admin top floor Room 35 Labour department Assistant 18000 btu carrier unit completely. 7. Admin top floor Room 37 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor Room 40 18000 btu Panasonic wall mount unit in the entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 9. Admin top floor Room 43 18000 btu carrier 1. Admin top floor floor Room 43 18000 btu carrier 1. Admin top floor enter Room 43 18000 btu carrier 1. Admin top floor centre Room 43 18000 btu carrier 1. Admin top floor centre Room 43 18000 btu carrier 1.			
Morks required. Admin HR top floor back office left — Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with retrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back office right — Room 34 18000 btu carrier Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. Admin HR top floor back first right front back—Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front—Room 34 18000 btu carrier Admin HR top floor back first left front—Room 34 18000 btu carrier Admin HR top floor back first left front—Room 34 18000 btu carrier Admin top floor Room 35 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely.		the onsite company attendance register at institution project leader	
Admin HR top floor back office left – Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back office right – Room 34 18000 btu carrier Admin HR top floor back office right – Room 34 18000 btu carrier Admin HR top floor back first right front back – Room 34 18000 btu carrier Admin HR top floor back first right front back – Room 34 18000 btu carrier Seplace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front– Room 34 18000 btu carrier Admin HR top floor back first left front– Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Admin top floor Room 36 Labour department Assistant 18000 btu carrier 6.1 Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier 8.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor fett Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor left Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18		office can be signed and works can start.	
Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back office right – Room 34 18000 btu carrier Repair gas leak and charge with refrigerant and replace evaporator lan and clean and disinfect indoor unit completely. Admin HR top floor back first right front back – Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front– Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor left Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier	6.	·	
charge with refrigerant gas and clean and disinfect indoor unit completely. Admin IR top floor back office right – Room 34 18000 btu carrier [an and clean and disinfect indoor unit completely.] Admin IR top floor back first right front back—Room 34 18000 btu carrier [an and clean and disinfect indoor unit completely.] Admin IR top floor back first right front back—Room 34 18000 btu carrier [an and clean and disinfect indoor unit completely.] Admin IR top floor back first left front—Room 34 18000 btu carrier [an and disinfect indoor unit completely.] Admin IR top floor back first left front—Room 34 18000 btu carrier [an and disinfect and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier [and to tharge with gas and clean and disinfect entire unit completely.] Admin top floor Room 36 Labour department Assistant 18000 btu carrier [and to tharge with gas and clean and disinfect entire unit completely.] Admin top floor Room 37 18000 btu carrier [and to tharge gas leak and charge with gas and clean and disinfect entire unit completely.] Admin top floor Room 37 18000 btu carrier [and to tharge gas leak and charge with gas and clean and disinfect entire unit completely.] Admin top floor Room 37 18000 btu carrier [and to tharge gas leak and charge with gas and clean and disinfect entire unit completely.] Admin top floor Room 40 18000 btu Panasonic wall mount unit in its entirely and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor centre Room 43 18000 btu carrier [and to the plant of the plant of the project leader.] Admin top floor centre Room 43 18000 btu carrier [and to the plant of	6.1		
completely. Admin HR top floor back office right – Room 34 18000 btu carrier 2.1 Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. 3.1 Admin HR top floor back first right front back.—Room 34 18000 btu carrier 3.2 Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 4. Admin HR top floor back first left front—Room 34 18000 btu carrier 4.4.1 Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 5. Admin top floor Room 35 18000 btu carrier 6.5.1 Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. 6. Admin top floor Room 36 Labour department Assistant 18000 btu carrier 6.1. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.2. Admin top floor Room 37 18000 btu carrier 6.3. Admin top floor Room 37 18000 btu carrier 6.4. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.8. Admin top floor Room 40 18000 btu Panasonic wall mount unit completely. 6.8. Admin top floor Room 40 18000 btu Panasonic wall mount unit in completely. 6.9. Admin top floor Room 41 18000 btu Carrier 6.9. Admin top floor floor floor floor floor the Room 43 18000 btu carrier 6.9. Admin top floor floor floor floor floor wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 6. Admin top floor eff Room 43 18000 btu carrier 6. Admin top floor eff Room 43 18000 btu carrier 7. Admin top floor eff Room 43 18000 btu carrier 7. Admin top floor eff Room 43 18000 btu carrier 7. Admin top floor eff Room 43 18000 btu carrier 7. Admin top floor	6.1.1	Replace compressor capacitor, Compressor drier, flush unit and	
2.1 Admin HR top floor back office right – Room 34 18000 btu carrier Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. 3.1 Admin HR top floor back first right front back—Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 4.4 Admin HR top floor back first left front—Room 34 18000 btu carrier Admin HR top floor back first left front—Room 34 18000 btu carrier 4.4.1 Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 5.5 Admin top floor Room 35 18000 btu carrier 5.6.1 Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. 6.6.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.7.1 Admin top floor Room 37 18000 btu carrier 6.7.1.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.8 Admin top floor Room 40 18000 btu Panasonic wall mount unit disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 8.9 Admin top floor entificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 8.9 Admin top floor centre Room 43 18000 btu carrier 8.9 Admin top floor centre Room 43 18000 btu carrier 8.9 Admin top floor centre Room 43 18000 btu carrier 9.9 Admin top floor centre Room 43 18000 btu carrier 9.9 Admin top floor centre Room 43 18000 btu carrier 9.9 Admin top floor centre Room 43 18000 btu carrier		charge with refrigerant gas and clean and disinfect indoor unit	
2.1 Repair gas leak and charge with refrigerant and replace evaporator fan and clean and disinfect indoor unit completely. 3.1 Admin HR top floor back first right front back—Room 34 18000 btu carrier 3.3.1 Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 4. Admin HR top floor back first left_front—Room 34 18000 btu carrier 4.4.1 Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 5. Admin top floor Room 35 18000 btu carrier 5.5.1 Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. 6. Admin top floor Room 36 Labour department Assistant 18000 btu carrier 6. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 7. Admin top floor Room 37 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor Room 40 18000 btu Panasonic wall mount unit disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 8. Admin top floor left Room 43 18000 btu carrier 8. Admin top floor centre Room 43 18000 btu carrier 8. Admin top floor centre Room 43 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor centre Room 43 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor centre Room 43 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor centre Room 43 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire		completely.	
fan and clean and disinfect indoor unit completely. Admin HR top floor back first right front back—Room 34 18000 btu carrier 3.1 Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. 4. Admin HR top floor back first left front—Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 5. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. 6. Admin top floor Room 36 Labour department Assistant 18000 btu carrier 6. Admin top floor Room 37 18000 btu carrier 6. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 7. Admin top floor Room 37 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor Room 40 18000 btu Panasonic wall mount unit in completely. 8. Admin top floor Room 40 18000 btu Panasonic wall mount unit in the entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 8. Admin top floor left Room 43 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor left Room 43 18000 btu carrier 8. Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8. Admin top floor centre Room 43 18000 btu carrier 8. Admin top floor centre Room 43 18000 btu carrier 8. Admin top floor centre Room 43 18000 btu carrier 8. Admin top floor centre Room 43 18000 btu carrier	6.2	Admin HR top floor back office right - Room 34 18000 btu carrier	
Admin HR top floor back first right front back—Room 34 18000 btu carrier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left_front—Room 34 18000 btu carrier Admin HR top floor back first left_front—Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely.	6.2.1	Repair gas leak and charge with refrigerant and replace evaporator	
Sarier Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front—Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely.		fan and clean and disinfect indoor unit completely.	
Replace compressor capacitor, Compressor drier, flush unit and charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front—Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Seplace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely.	6.3	Admin HR top floor back first right front back-Room 34 18000 btu	
charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front—Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 5 Admin top floor Room 35 18000 btu carrier Seplace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Admin top floor Room 37 18000 btu carrier Admin top floor Room 40 18000 btu Panasonic wall mount unit completely. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely.		carrier	
charge with refrigerant gas and clean and disinfect indoor unit completely. Admin HR top floor back first left front—Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 5 Admin top floor Room 35 18000 btu carrier Seplace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Admin top floor Room 37 18000 btu carrier Admin top floor Room 40 18000 btu Panasonic wall mount unit completely. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely.	6.3.1	Replace compressor capacitor, Compressor drier, flush unit and	
completely. Admin HR top floor back first left front—Room 34 18000 btu carrier Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 5.5 Admin top floor Room 35 18000 btu carrier 8.5.1 Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier 8.6.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier 8.7.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.8 Admin top floor Room 40 18000 btu Panasonic wall mount unit 8.8.1 Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 8.9 Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.10 Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.10 Admin top floor centre Room 43 18000 btu carrier 1.11 Repair gas leak and charge with gas and clean and disinfect entire unit completely.			
Admin HR top floor back first left front—Room 34 18000 btu carrier 4.1 Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. 4.5 Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. 4.6 Admin top floor Room 36 Labour department Assistant 18000 btu carrier 5.7 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 5.7 Admin top floor Room 37 18000 btu carrier 6.7.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.8 Admin top floor Room 40 18000 btu Panasonic wall mount unit of floor Room 40 18000 btu Panasonic wall mount unit dissurbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 6.9 Admin top floor left Room 43 18000 btu carrier 7.9 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.10 Admin top floor left Room 43 18000 btu carrier 8.11 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.12 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.13 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.14 Repair gas leak and charge with gas and clean and disinfect entire			
Replace unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire	6.4		
electrical COC certificate. Make good all disturbed brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Benair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Benair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier	6.4.1		
paint work to the satisfaction of institution Project leader. Admin top floor Room 35 18000 btu carrier Estate and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Estate and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Estate and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Admin top floor Room 37 18000 btu carrier Estate and charge with gas and clean and disinfect entire unit completely. Estate and electrical conclusion wall mount unit Estate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Estate and electrical conclusion end of the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Estate and electrical conclusion end of the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Estate and electrical conclusion end of the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Estate and electrical conclusion end of the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Estate and electrical conclusion end of the satisfaction of institution Project leader. Estate and electrical conclusion end of the satisfaction of institution Project leader. Estate and electrical conclusion end of the satisfaction of institution end of the satisfaction en			
Admin top floor Room 35 18000 btu carrier 8.5.1 Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. 8.6.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.7.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.7.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.8.2 Admin top floor Room 37 18000 btu carrier 8.8.3 Admin top floor Room 40 18000 btu Panasonic wall mount unit completely. 8.8.4 Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 8.9 Admin top floor left Room 43 18000 btu carrier 8.9.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 8.10 Admin top floor centre Room 43 18000 btu carrier 8.10.1 Repair gas leak and charge with gas and clean and disinfect entire			
Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Repair gas leak and charge with gas and clean and disinfect entire unit completely. Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire	6.5		
charge with gas and clean and disinfect entire unit completely. Admin top floor Room 36 Labour department Assistant 18000 btu carrier 6.6.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.7 Admin top floor Room 37 18000 btu carrier 6.7.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.8 Admin top floor Room 40 18000 btu Panasonic wall mount unit 6.8.1 Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 6.9 Admin top floor left Room 43 18000 btu carrier 6.9.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.10 Admin top floor centre Room 43 18000 btu carrier 6.10.1 Repair gas leak and charge with gas and clean and disinfect entire	6.5.1		
Admin top floor Room 36 Labour department Assistant 18000 btu carrier 6.6.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.7 Admin top floor Room 37 18000 btu carrier 6.7.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.8 Admin top floor Room 40 18000 btu Panasonic wall mount unit 6.8.1 Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 6.9 Admin top floor left Room 43 18000 btu carrier 6.9.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.10 Admin top floor centre Room 43 18000 btu carrier 6.10.1 Repair gas leak and charge with gas and clean and disinfect entire			
carrier 6.6.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.7 Admin top floor Room 37 18000 btu carrier 6.7.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.8 Admin top floor Room 40 18000 btu Panasonic wall mount unit 6.8.1 Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 6.9 Admin top floor left Room 43 18000 btu carrier 6.9.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.10 Admin top floor centre Room 43 18000 btu carrier 6.10.1 Repair gas leak and charge with gas and clean and disinfect entire	6.6		
Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire	3.0		
unit completely. Admin top floor Room 37 18000 btu carrier 3.7.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 3.8 Admin top floor Room 40 18000 btu Panasonic wall mount unit 3.8.1 Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 3.9 Admin top floor left Room 43 18000 btu carrier 3.9.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 3.10 Admin top floor centre Room 43 18000 btu carrier 3.10.1 Repair gas leak and charge with gas and clean and disinfect entire	6.6.1		
Admin top floor Room 37 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire	0.0.1		
Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire	6.7		
unit completely. Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire			
Admin top floor Room 40 18000 btu Panasonic wall mount unit Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire	U.7.1	1	
Replace Panasonic wall mount unit in its entirety and issue COC refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire	6.8		
refrigeration certificate and electrical COC certificate. Make good all disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 6.9 Admin top floor left Room 43 18000 btu carrier 6.9.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.10 Admin top floor centre Room 43 18000 btu carrier 6.10.1 Repair gas leak and charge with gas and clean and disinfect entire			
disturbed/exposed Metal, glass, brick, plaster and paint work to the satisfaction of institution Project leader. 6.9 Admin top floor left Room 43 18000 btu carrier 6.9.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.10 Admin top floor centre Room 43 18000 btu carrier 6.10.1 Repair gas leak and charge with gas and clean and disinfect entire	0.0.1		
satisfaction of institution Project leader. 5.9 Admin top floor left Room 43 18000 btu carrier 6.9.1 Repair gas leak and charge with gas and clean and disinfect entire unit completely. 6.10 Admin top floor centre Room 43 18000 btu carrier 6.10.1 Repair gas leak and charge with gas and clean and disinfect entire			
Admin top floor left Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire			
Repair gas leak and charge with gas and clean and disinfect entire unit completely. Admin top floor centre Room 43 18000 btu carrier Repair gas leak and charge with gas and clean and disinfect entire	6.0		
unit completely. 3.10 Admin top floor centre Room 43 18000 btu carrier 5.10.1 Repair gas leak and charge with gas and clean and disinfect entire			
6.10 Admin top floor centre Room 43 18000 btu carrier 6.10.1 Repair gas leak and charge with gas and clean and disinfect entire	0.9.1		
3.10.1 Repair gas leak and charge with gas and clean and disinfect entire	0.10		
unit completely.	6.10.1		
		unit completely.	



6.11	Admin top floor right Room 43 18000 btu carrier	
	Replace compressor capacitor, compressor, drier, flush unit and charge with gas and clean and disinfect entire unit completely.	
7.	Daily works completion requirements	
7.1	Contractor staff to report for work at 07H45	
7.2	Contractor project leader shall have his staff to clean and clear work site and be ready for daily work completion inspection at 15H30 each working day on site	
7.3	Job card (Annexure A attached) will be completed by company project leader and signed off by Institution project leader once the work done is satisfactory completed. Note: Should work not be satisfactory, the contractor project leader shall redirect staff to remedy the unsatisfactory work the next working day prior continuing with the rest of the works.	
7.4	Refrigeration and electrical COC is to be completed on each machine the day of each unit completion before job card is signed off and prior continuing with the works the next day	
8.	Compulsory contractors project leader Friday works progress meetings to be attended (From 10H00) with maintenance departmental official.(minutes will be taken)	
9.	Works completion requirements	
9.1	The last day of work, the company project leader will prepare the work completion document and if works is done satis factory, will be singed off by institution projects leader.	
9.2	The company is requested to keep copies of all suppliers' invoices of all items bought out and works related document/s before submitting the original documents for payment at finance department. Should any document become misplaced the contractor will be requested to submit relevant document in order to process payment forsaid works.	

3	Does a sample need	to be submitted?	No(select ont	ion 3.1	or 3.2)
J.	Dues a samble meeu	to be submitted:	11013CICCL UDI		01 0.2

- 3.1. Deadline for submission if Yes: Date ____/____ Time11:00 Place: Maintenance Department
- 3.2. Specify that samples must be made available when requested in writing. No

4. Penalties to be noted by the suppliers:

4.1. If the supplier fails to deliver any or all of the goods or to perform the services within the period(s) specified in the contract, the purchaser shall, without prejudice to its other remedies under the contract, **deduct from the contract price**, as a penalty, a sum calculated on the delivered price of the delayed goods or unperformed services using the current prime interest rate calculated for each day of the delay until actual delivery or performance.

5. What is the evaluation criteria / special terms and conditions to be advertised?

List evaluation criteria / special terms and conditions to be advertised (if applicable)						
1.	Pre-qualification criteria	re-qualification criteria Completed material bill of quantities				
2.	Administrative	Does the offer comply to stipulated administrative requirements?				
3.	Conformance:	SARACCA A4 certified copy of refrigeration gas card attached to tender document.				
4.	Performance:	Will/does the product/service fulfil its performance obligation, in a manner that releases the supplier from all liabilities under the contract?				
5.	Features:	What characteristics does the product or service have?				
6.	Reliability:	How long can a product go between failures and the need for maintenance? (guarantee)				
7.	Durability:	What is the useful life for the product? How will the product hold up under extended use?				
8.	Serviceability:	How easy is it to repair, maintain or support the product or service? (customer support)				
9.	Ability & Capacity The ability and capacity of the vendor to execute the contract					

STANDARD QUOTE DOCUMENTATION SUPPLY CHAIN MANAGEMENT OVER R30 000.00 YOU ARE HEREBY INVITED TO QUOTE FOR REQUIREMENTS AT: KING EDWARD VIII HOSPITAL DATE ADVERTISED: 2021-05-10 CLOSING DATE: 2021-04-30 FACSIMILE NUMBER: 031 205 6722 E-MAIL ADDRESS: PHYSICAL ADDRESS: GATE 2 FRANCIOS ROAD CONGELLA 4013 ZNQ NUMBER: KEV 125\ 21 DESCRIPTION: ATTEND TO HR SPLIT UNIT AC REPAIR CONTRACT PERIOD..... **VALIDITY PERIOD 60 Days** SARS PIN... (if applicable) CENTRAL SUPPLIER DATABASE REGISTRATION (CSD) NO. UNIQUE REGISTRATION REFERENCE DEPOSITED IN THE QUOTE BOX SITUATED AT (STREET ADDRESS) Bidders should ensure that quotes are delivered timeously to the correct address. If the quote is late, it will not be accepted for consideration. The quote box is open from 08:00 to 15:30. ALL QUOTES MUST BE SUBMITTED ON THE OFFICIAL FORMS - (NOT TO BE RE-TYPED) THIS QUOTE IS SUBJECT TO THE PREFERENTIAL PROCUREMENT POLICY FRAMEWORK ACT AND THE PREFERENTIAL PROCUREMENT REGULATIONS, 2011, THE GENERAL CONDITIONS OF CONTRACT (GCC) AND, IF APPLICABLE, ANY OTHER SPECIAL CONDITIONS OF CONTRACT. THE FOLLOWING PARTICULARS MUST BE FURNISHED (FAILURE TO DO SO WILL RESULT IN YOUR QUOTE BEING DISQUALIFIED) NAME OF BIDDER POSTAL ADDRESS STREET ADDRESS TELEPHONE NUMBER CELLPHONE NUMBER E-MAIL ADDRESS VAT REGISTRATION NUMBER (If VAT vendor) YES NO HAS A B-BBEE STATUS LEVEL VERIFICATION CERTIFICATE BEEN SUBMITTED? (SBD 6.1)

[A B-BBEE STATUS LEVEL VERIFICATION CERTIFICATE/SWORN AFFIDAVIT (FOR EMES& QSEs) MUST BE SUBMITTED IN ORDER

TO QUALIFY FOR PREFERENCE POINTS FOR B-BBEE]

OFFICIAL PRICE PAGE FOR QUOTATIONS	ZNQ NUMBER: KEV 125\ 21
DESCRIPTION: ATTEND TO HR SPLIT UNIT AC REPAIR	R
SIGNATURE OF BIDDER [By signing this document I hereby agree to all terms and conditions]	
CAPACITY LINDER WHICH THIS QUOTE IS SIGNED	

Item No	Quantity	antity Description	Brand &	Country of manufacture	Price	
			model	manufacture	R	
1.	11	ATTEND TO HR SPLIT UNIT AC REPAIR				
						\neg
						7
						_
					_	7
				- t	_	7
						\dashv
				1		=
			+	-	_	-
						-
					-	-
					-	-
	_			+	_	-
	1				-	-
	-				_	-
	-				_	-
	-				_	
						_
	-					
ALUE AD	DED TAX @	15% (Only if VAT Vendor) RICE (VALIDITY PERIOD 60 Days)				

Does This Offer Comply With The Specification?	Does The Article Conform To The S.A.N.S. / S.A.B.S. Specification?		
Is The Price Firm?	State Delivery Period E.G. E.G. 1day, 1week		
Enquiries regarding the quote may be directed to:	2602446	Enquiries regarding technical information may be directed to:	
Contact Person: KHULANI Tel: 03.1	200224Q.	Contact Person: EUGENE Tel: 0313603463	

DECLARATION OF INTEREST

1. - -	blood relationship, may make limited quote or proposal). In employed by the state, or to particular declare his/her position in relating the bidder is employed by the legal person on whose evaluation and or adjudicate	an offer or offers in terms of this invit view of possible allegations of favour persons connected with or related to tion to the evaluating/adjudicating aut he state; and/or behalf the bidding document is sign	ation to quote (includes a price quitism, should the resulting quote, them, it is required that the biddehority where- ed, has a relationship with person wn that such a relationship exists	ons employed by the state, including a uotation, advertised competitive quote, or part thereof, be awarded to persons er or his/her authorised representative ans/a person who are/is involved in the between the person or persons for or lication of the quote
2.		pove, the following questionnaire mus	•	•
2.2.	Identity Number: Position occupied in the Com	tative pany (director, trustee, shareholder²):	2.5. Tax Reference Number:	
2.8. 2.8.1	employee / persal numbers m Are you or any person conner .If so, furnish the following par Name of person / director / tru	nust be indicated in paragraph 3 below cted with the bidder presently employ ticulars: stee / shareholder/ member:	v. ed by the state?	reference numbers and, if applicable, [TICK APPLICABLE] [YES NO
	Name of state institution at wh	ich you or the person connected to th	e bidder is employed:	
2.8.2 (Note: 1	 If you are presently employ in the public sector? If yes, did you attach proceeds 	ed by the state, did you obtain the ap of of such authority to the quote docur authority, where applicable, may resu	propriate authority to undertake re nent? It in the disqualification of the quo	emunerative work outside employment YES NO
2.8.2	.2. If no, furnish rea	sons for non-submission of such prod	f	
	state in the previous twelve m	y or the company's directors / trustee onths?		eir spouses conduct business with the YES NO
2.10	Do you, or any person connect may be involved with the eval	cted with the bidder, have any relation uation and or adjudication of this quo	ship (family, friend, other) with a pate?	person employed by the state and who YES NO
2.11. 2.11.	Are you, or any person conne employed by the state who m 1. If so, furnish particulars:	cted with the bidder, aware of any rela ay be involved with the evaluation and	ationship (family, friend, other) bet d or adjudication of this quote?	ween any other bidder and any person YES NO
	or not they are bidding for this	rustees / snarenoiders / members o contract?		any other related companies whether YES NO
3.	Full details of directors / trus The Department Of Health wil to ensure that their details are	stees / members / shareholders. I validate details of directors / truste	ees / members / shareholders or he Department cannot validate th	n CSD. It is the suppliers' responsibility e information on CSD, the quote will e 4 (a) 2016/17.
4	DECLARATION			
	IE UNDERSIGNED (NAM NISHED IN PARAGRAPF		CERT	FY THAT THE INFORMATION
I AC PRO	CEPT THAT THE STATE VE TO BE FALSE.	MAY REJECT THE QUOTE OF	R ACT AGAINST ME SHOU	LD THIS DECLARATION
	e of bidder	Signature	Position	Date
	any national or provincial departmen	nt national or provincial authorized	a)	
a) b)	constitutional institution within the me Act, 1999 (Act No. 1 of 1999); any municipality or municipal entity;	nt, national or provincial public entity or eaning of the Public Finance Management	c) provincial legislature;d) national Assembly or the national Ce) Parliament.	ouncil of provinces; or

^{*}Shareholder* means a person who owns shares in the company and is actively involved in the management of the enterprise or business and exercises control over the enterprise.

SPECIAL CONTRACT CONDITIONS OF QUOTATIONS

1. AMENDMENT OF CONTRACT

1.1. Any amendment to or renunciation of the provisions of the contract shall at all times be done in writing and shall be signed by both parties.

2. CHANGE OF ADDRESS

2.1. Bidders must advise the Department of Health (institution where the offer was submitted) should their address (*domicilium citandi et executandi*) details change from the time of bidding to the expiry of the contract.

3. GENERAL CONDITIONS ATTACHED TO THIS QUOTATION

- 3.1. The institution is under no obligation to accept the lowest or any quote.
- 3.2. The price quoted must include VAT (if VAT vendor). However, it must be noted that the department reserves the right to evaluate all quotations excluding VAT as some bidders may not be VAT vendors.
- 3.3. The bidder must ensure the correctness & validity of quote:
 - (i) that the price(s), rate(s) & preference quoted cover all for the work/item (s) & accept that any mistakes regarding the price (s) & calculations will be at the bidder's risk
- 3.4. The bidder must accept full responsibility for the proper execution & fulfilment of all obligations conditions devolving on under this agreement, as the Principal (s) liable for the due fulfilment of this contract.
- 3.5. This quotation will be evaluated based on the 80/20 points system, specification & correctness of information. All required documentation must be completed in full and submitted.
- 3.6. Offers must comply strictly with the specification.
- 3.7. Only offers that meet or are greater than the specification will be considered.
- 3.8. Late quotes will not be considered.
- 3.9. Expired product/s will not be accepted. All products supplied must be valid for a minimum period of six months.
- 3.10. A bidder not registered on the Central Suppliers Database or verification has failed will not be considered.
- 3.11. All delivery costs must be included in the quote price, for delivery at the prescribed destination.
- 3.12. Only firm prices will be accepted. Such prices must remain firm for the contract period. Non-firm prices (including rates of exchange variations) will not be considered.
- 3.13. In cases where different delivery points influence the pricing, a separate pricing schedule must be submitted for each delivery point.
- 3.14. In the event of a bidder having multiple quotes, only the cheapest according to specification will be considered. Furthermore a verification will be done to identify if bidders have multiple companies and are quoting (cover-quoting) for this bid. In such instances only the cheapest bid according to specification will be considered.

4. SPECIAL INSTRUCTIONS AND NOTICES TO BIDDERS REGARDING THE COMPLETION OF THIS QUOTATION.

- 4.1. Unless inconsistent with or expressly indicated otherwise by the context, the singular shall include the plural and vice versa and with words importing the masculine gender shall include the feminine and the neuter.
- 4.2. Under no circumstances whatsoever may the quotation/bid forms be retyped or redrafted. Photocopies of the original bid documentation may be used, but an original signature must appear on such photocopies.
- 4.3. The bidder is advised to check the number of pages and to satisfy himself that none are missing or duplicated.
- 4.4. Quotation submitted must be complete in all respects.
- 4.5. Any alteration made by the bidder must be initialled.
- 4.6. Use of correcting fluid is prohibited
- 4.7. Quotation will be opened in public as soon as practicable after the closing time of quotation.
- 4.8. Where practical, prices are made public at the time of opening quotations.
- 4.9. If it is desired to make more than one offer against any individual item, such offers should be given on a photocopy of the page in question. Clear indication thereof must be stated on the schedules attached.

5. SPECIAL INSTRUCTIONS REGARDING HAND DELIVERED QUOTATIONS

- 5.1. Quotation shall be lodged at the address indicated not later than the closing time specified for their receipt, and in accordance with the directives in the quotation documents.
- 5.2. Each quotation shall be addressed in accordance with the directives in the quotation documents and shall be lodged in a separate sealed envelope, with the name and address of the bidder, the quotation number and closing date indicated on the envelope. The envelope shall not contain documents relating to any quotation other than that shown on the envelope. If this provision is not complied with, such quotations/bids may be rejected as being invalid.
- 5.3. All quotations received in sealed envelopes with the relevant quotation numbers on the envelopes are kept unopened in safe custody until the closing time of the quotation/bids. Where, however, a quotation is received open, it shall be sealed. If it is received without a quotation/bid number on the envelope, it shall be opened, the quotation number ascertained, the envelope sealed and the quotation number written on the envelope.
- 5.4. A specific box is provided for the receipt of quotations, and no quotation found in any other box or elsewhere subsequent to the closing date and time of quotation will be considered.

- 5.5. No quotation/bid sent through the post will be considered if it is received after the closing date and time stipulated in the quotation documentation, and proof of posting will not be accepted as proof of delivery.
- 5.6. Quotation documents must not be included in packages containing samples. Such quotations may be rejected as being invalid.

6. SAMPLES

- 6.1. In the case of the quote document stipulating that samples are required, the supplier will be informed in due course when samples should be provided to the institution. (This decreases the time of safety and storage risk that may be incurred by the respective institution). The bidders sample will be retained if such bidder wins the contract.
- (i) If a company/s who has not won the quote requires their samples, they must advise the institution in writing of such.
- (ii) If samples are not collected within three months of close of quote the institution reserves the right to dispose of them at their discretion.
- 6.2. Samples must be made available when requested in writing or if stipulated on the document.
- (i) If a Bidder fails to provide a sample of their product on offer for scrutiny against the set specification when requested, their offer will be rejected. All testing will be for the account of the bidder.

7. COMPULSORY SITE INSPECTION / BRIEFING SESSION

7.1.	Bidders who fail to attend the compulsory meeting will be disqualified from the evaluation process.	
(i) (ii)	The institution has determined that a compulsory site meeting Date/ Time: Place	take place
Institution Stamp:		Institution Site Inspection / briefing session Official
		Full Name:
		Signature:
		Date:

8. STATEMENT OF SUPPLIES AND SERVICES

8.1. The contractor shall, when requested to do so, furnish particulars of supplies delivered or services executed. If he/she fails to do so, the Department may, without prejudice to any other rights which it may have, institute inquiries at the expense of the contractor to obtain the required particulars.

9. SUBMISSION AND COMPLETION OF SBD 6.1

9.1. Should a bidder wish to qualify for preference points they must complete a SBD 6.1 document. Failure by a bidder to provide all relevant information required, will result in such a bidder not being considered for preference point's allocation. The preferences applicable on the closing date will be utilized. Any changes after the closing date will not be considered for that particular quote.

10. TAX COMPLIANCE REQUIREMENTS

- 10.1. In the event that the tax compliance status has failed on CSD, it is the suppliers' responsibility to provide a SARS pin in order for the institution to validate the tax compliance status of the supplier.
- 10.2. In the event that the institution cannot validate the suppliers' tax clearance on SARS as well as the Central Suppliers Database, the quote will not be considered and passed over as non-compliant according to National Treasury Instruction Note 4 (a) 2016/17.

11. TAX INVOICE

- 11.1. A tax invoice shall be in the currency of the Republic of South Africa and shall contain the following particulars:
- (i) the name, address and registration number of the supplier:
- (ii) the name and address of the recipient;
- (iii) an individual serialized number and the date upon which the tax invoice is issued;
- (iv) a description and quantity or volume of the goods or services supplied;
- (v) the official department order number issued to the supplier;
- (vi) the value of the supply, the amount of tax charged;
- (vii) the words tax invoice in a prominent place.

12. PATENT RIGHTS

The supplier shall indemnify the KZN Department of Health (hear after known as the purchaser) against all third-party claims of infringement of patent, trademark, or industrial design rights arising from use of the goods or any part thereof by the purchaser.

13. PENALTIES

- 13.1. If at any time during the contract period, the service provider is unable to perform in a timely manner, the service provider must notify the institution in writing/email of the cause of and the duration of the delay. Upon receipt of the notification, the institution should evaluate the circumstances and, if deemed necessary, the institution may extend the service provider's time for performance.
- 13.2. In the event of delayed performance that extends beyond the delivery period, the institution is entitled to purchase commodities of a similar quantity and quality as a substitution for the outstanding commodities, without terminating the contract, as well as return commodities delivered at a later stage at the service provider's expense.
- 13.3. Alternatively, the institution may elect to terminate the contract and procure the necessary commodities in order to complete the contract. In the event that the contract is terminated the institution may claim damages from the service provider in the form of a penalty. The service provider's performance should be captured on the service provider database in order to determine whether or not the service provider should be awarded any contracts in the future.
- 13.4. If the supplier fails to deliver any or all of the goods or to perform the services within the period(s) specified in the contract, the purchaser shall, without prejudice to its other remedies under the contract, deduct from the contract price, as a penalty, a sum calculated on the delivered price of the delayed goods or unperformed services using the current prime interest rate calculated for each day of the delay until actual delivery or performance.

14. TERMINATION FOR DEFAULT

- 14.1. The purchaser, without prejudice to any other remedy for breach of contract, by written notice of default sent to the supplier, may terminate this contract in whole or in part:
- (i) if the supplier fails to deliver any or all of the goods within the period(s) specified in the contract,
- (ii) if the supplier fails to perform any other obligation(s) under the contract; or
- (iii) if the supplier, in the judgment of the purchaser, has engaged in corrupt or fraudulent practices in competing for or in executing the contract.
- 14.2. In the event the purchaser terminates the contract in whole or in part, the purchaser may procure, upon such terms and in such manner as it deems appropriate, goods, works or services similar to those undelivered, and the supplier shall be liable to the purchaser for any excess costs for such similar goods, works or services.
- 14.3. Where the purchaser terminates the contract in whole or in part, the purchaser may decide to impose a restriction penalty on the supplier by prohibiting such supplier from doing business with the public sector for a period not exceeding 10 years.
- 15. FAILURE TO COMPLY WITH ABOVE WILL RESULT IN YOUR QUOTE BEING PASSED OVER.

PREFERENCE POINTS CLAIM FORM IN TERMS OF THE PREFERENTIAL PROCUREMENT REGULATIONS 2017

This preference form must form part of all quotes invited. It contains general information and serves as a claim form for preference points for Broad-Based Black Economic Empowerment (B-BBEE) Status Level of Contribution

NB: BEFORE COMPLETING THIS FORM, BIDDERS MUST STUDY THE GENERAL CONDITIONS, DEFINITIONS AND DIRECTIVES APPLICABLE IN RESPECT OF B-BBEE, AS PRESCRIBED IN THE PREFERENTIAL PROCUREMENT REGULATIONS, 2017.

1. GENERAL CONDITIONS

- 1.1 The following preference point systems are applicable to all quotes:
 - the 80/20 system for requirements with a Rand value of up to R50 000 000 (all applicable taxes included); and
- 1.2 The value of this quote is estimated to not exceed R50 000 000 (all applicable taxes included) and therefore the 80/20 preference point system shall be applicable.
- 1.3 Points for this quote shall be awarded for:
 - (a) Price; and
 - (b) B-BBEE Status Level of Contributor.
- 1.4 The maximum points for this quote is allocated as follows:

	POINTS
PRICE	80
B-BBEE STATUS LEVEL OF CONTRIBUTOR	20
Total points for Price and B-BBEE must not exceed	100

- Failure on the part of a bidder to submit proof of B-BBEE Status level of contributor together with the quote, will be interpreted to mean that preference points for B-BBEE status level of contribution are not claimed.
- 1.6 The purchaser reserves the right to require of a bidder, either before a quote is adjudicated or at any time subsequently, to substantiate any claim in regard to preferences, in any manner required by the purchaser.

2. DEFINITIONS

- (a) "B-BBEE" means broad-based black economic empowerment as defined in section 1 of the Broad-Based Black Economic Empowerment Act;
- (b) "B-BBEE status level of contributor" means the B-BBEE status of an entity in terms of a code of good practice on black economic empowerment, issued in terms of section 9(1) of the Broad-Based Black Economic Empowerment Act;
- (c) "bid" means a written offer in a prescribed or stipulated form in response to an invitation by an organ of state for the provision of goods or services, through price quotations, advertised competitive bidding processes or proposals;
- (d) "Broad-Based Black Economic Empowerment Act" means the Broad-Based Black Economic Empowerment Act, 2003 (Act No. 53 of 2003);
- (e) "EME" means an Exempted Micro Enterprise in terms of a code of good practice on black economic empowerment issued in terms of section 9 (1) of the Broad-Based Black Economic Empowerment Act;
- (f) "functionality" means the ability of a tenderer to provide goods or services in accordance with specifications as set out in the tender documents.
- (g) "prices" includes all applicable taxes less all unconditional discounts;
- (h) "proof of B-BBEE status level of contributor" means:
 - 1) B-BBEE Status level certificate issued by an authorized body or person;
 - 2) A sworn affidavit as prescribed by the B-BBEE Codes of Good Practice;
 - Any other requirement prescribed in terms of the B-BBEE Act;
- (i) "QSE" means a qualifying small business enterprise in terms of a code of good practice on black economic empowerment issued in terms of section 9 (1) of the Broad-Based Black Economic Empowerment Act;
- "rand value" means the total estimated value of a contract in Rand, calculated at the time of bid invitation, and includes all applicable taxes;

3. POINTS AWARDED FOR PRICE

3.1 THE 80/20 PREFERENCE POINT SYSTEMS

A maximum of 80 points is allocated for price on the following basis:

$$Ps = 80 \left(1 - \frac{Pt - P\min}{P\min}\right)$$
 Where

Ps = Points scored for price of bid under consideration

Pt = Price of bid under consideration
Pmin = Price of lowest acceptable bid

4. POINTS AWARDED FOR B-BBEE STATUS LEVEL OF CONTRIBUTOR

4.1 In terms of Regulation 6 (2) and 7 (2) of the Preferential Procurement Regulations, preference points must be awarded to a bidder for attaining the B-BBEE status level of contribution in accordance with the table below:

B-BBEE Status Level of Contributor	Number of points (80/20 system)
1	20
22	18
3	14
4	12
5	8
6	6
7	4
8	2
Non-compliant contributor	0

E	חום	DECL	ADA	MOITA
n	RIII	111-11	u_{K}	3 I II BIN

- 5.1 Bidders who claim points in respect of B-BBEE Status Level of Contribution must complete the following:
- 6. B-BBEE STATUS LEVEL OF CONTRIBUTOR CLAIMED IN TERMS OF PARAGRAPHS 1.4 AND 4.1
- 6.1 B-BBEE Status Level of Contributor: =(maximum of 20 points)

(Points claimed in respect of paragraph 7.1 must be in accordance with the table reflected in paragraph 4.1 and must be substantiated by relevant proof of B-BBEE status level of contributor.

7.	SUB-CONTRACTING	(Tick applicable box)		
7.1	Will any portion of the contract be sub-contracted?	YES NO		

7.1.1 If yes, indicate:

ii) The name of the sub-contractor......
The B-BBEE status level of the sub-contractor......

8. Whether the sub-contractor is an EME or QSE (Tick applicable box)

iv) Specify, by ticking the appropriate box, if subcontracting with an enterprise in terms of Preferential Procurement Regulations 2017:

Designated Group: An EME or QSE which is at last 51% owned by:	EME √	QSE √
Black people		
Black people who are youth		
Black people who are women		
Black people with disabilities		
Black people living in rural or underdeveloped areas or townships		
Cooperative owned by black people		
Black people who are military veterans		
OR		-1:
Any EME		
Any QSE		1

9.	DECLAR	DECLARATION WITH REGARD TO COMPANY/FIRM			
9.1	Name	Name of company/firm:			
9.2	VAT registration number:				
9.3	Company registration number:				
9.4	TYPE	TYPE OF COMPANY/ FIRM [TICK APPLICABLE BOX]			
	0 0 0 0	Partnership/Joint Venture / Consortium One person business/sole propriety Close corporation Company (Pty) Limited			
9.5 DESCRIBE PRINCIPAL BUSINESS ACTIVITIES					
9.6	COMP	ANY CLASSIFICATION [TICK APPLICABLE B Manufacturer Supplier Professional service provider Other service providers, e.g. transporter, etc.	OX]		
9.7	Total n	umber of years the company/firm has been in b	ousiness:		
9.8	the B-f	I/we, the undersigned, who is / are duly authorised to do so on behalf of the company/firm, certify that the points claimed, based on the B-BBE status level of contributor indicated in paragraphs 1.4 and 6.1 of the foregoing certificate, qualifies the company/ firm for the preference(s) shown and I / we acknowledge that:			
	i) The information furnished is true and correct;				
	ii) Ti	ii) The preference points claimed are in accordance with the General Conditions as indicated in paragraph 1 of this form;			
	iii) In the event of a contract being awarded as a result of points claimed as shown in paragraphs 1.4 and 6.1, the contractor may be required to furnish documentary proof to the satisfaction of the purchaser that the claims are correct;				
	iv) If ha	iv) If the B-BBEE status level of contributor has been claimed or obtained on a fraudulent basis or any of the conditions of contract have not been fulfilled, the purchaser may, in addition to any other remedy it may have —			
	(a) disqualify the person from the bidding process;		s;		
	(b)	recover costs, losses or damages it has incur	rred or suffered as a result of that person's conduct;		
	 (c) cancel the contract and claim any damages whi arrangements due to such cancellation; 		which it has suffered as a result of having to make less favourable		
	(d) recommend that the bidder or contractor, its shareholders and directors, or only the shareholders and directors who acted on a fraudulent basis, be restricted by the National Treasury from obtaining business from any organ of state for a period not exceeding 10 years, after the audi alteram partem (hear the other side) rule has been applied; and				
	(e) forward the matter for criminal prosecution.				
		ESSES	SIGNATURE(S) OF BIDDERS(S) DATE:		
	2		ADDRESS		