

SharePoint

Kate Primrose ▾ ?



KZN HEALTH

KZN Health Intranet

Search this site


[HOME](#) [CORPORATE INFORMATION](#) [COMPONENTS](#) [DIRECTORY](#) [DISTRICT OFFICES](#) [HEALTH FACILITIES](#)

KZN Health > Components > Supply Chain Management

AdvertQuote



Quotation Advert

Opening Date:	2022-07-14	
Closing Date:	2022-07-22	
Closing Time:	11:00	

INSTITUTION DETAILS

Institution Name:	Provincial Pharmaceutical Supply Depot	<input checked="" type="checkbox"/>
Province:	KwaZulu-Natal	
Department or Entity:	Department of Health	
Division or section:	Central Supply Chain Management	
Place where goods / services is required	PPSD	
Date Submitted	2022-07-14	

ITEM CATEGORY AND DETAILS

Quotation Number:	ZNQ: 0016/23	
Item Category:	Services	<input checked="" type="checkbox"/>
Item Description:	Repairs To Faulty Pallet Jacks	

Quantity (if supplies) 17

COMPULSORY BRIEFING SESSION / SITE VISIT

Select Type:	Compulsory Site Visit	<input checked="" type="checkbox"/>
Date :	2022-07-19	
Time:	11h00	
Venue:	PPSD Premises	

QUOTES CAN BE COLLECTED FROM: PPSD / Intranet

QUOTES SHOULD BE DELIVERED TO: PPSD Tender Box / ppsd.acquisitions@kznhealth.gov.za

ENQUIRIES REGARDING THE ADVERT MAY BE DIRECTED TO:

Name:	Thandazile / Nonjabulo
Email:	primrose.xate@kznhealth.gov.za / nonjabulo.gumede2@kznhealth.gov.za
Contact Number:	031 469 8339

Finance Manager Name:

M/S Naicker

Finance Manager Signature:

No late quotes will be considered

Print this page

Site Updated: 14 July, 2022, 09:11 am

The materials on this website may be copied for non-commercial use as long as our copyright notice and website address are included.
Copyright © KwaZulu-Natal Department of Health, 2000

Contact the Web Administrator



health

Department:
Health
PROVINCE OF KWAZULU-NATAL

1 Higginson Highway, Mobeni, 4052
Private Bag X03, Mobeni, 4060
Tel: 031 4698300 Fax: 031 4629158 Email: Thandeka.Njapha@kznhealth.gov.za
www.kznhealth.gov.za

DIRECTORATE:
PHARMACEUTICAL SERVICES

SCOPE OF WORK:
Repairs to 3 ton Pallet Jacks (Quantity 17)
Specification

- Fit new seal kit
- Heat / straighten where needed
- Clean, flush and lubricate
- Re-seal all ball and check valves
- Set and test load restrictor/s
- Change bearings where needed
- Paint and test scope of work

Scope of works:
Quantity = 17 Faulty Pallet Jacks (3 ton)

1. Pallet jack no. 45 (B/C: DOH717969)
Replace with:
PU/PTB-20050H/20
200mm Polyurethane Steer Wheel with 200mm Ball Bearing
PU/PTB-08096/20
86mm x 96mm Polyurethane Pallet with 20mm Ball bearing
2. Pallet jack no. 40 (B/C: AA700636)
Replace with:
PU/PTB-20050H/20
200MM POLYURETHANE Steer Wheel with 20mm Ball Bearing
PU/PTB-08096/20
86MM x 96MM Polyurethane Pallet with 20mm Ball bearing
3. Pallet jack no. 43 (B/C: DOH717172)
Replace with:
PU/PTB-20050H/20
200mm Polyurethane Steer Wheel with 20mm Ball Bearing
PJPU/WPR9680
96mm x 80mm Flat Polyurethane Pallet Jack Roller
4. Pallet jack no. 31 (B/C: DOH082567)
Replace with:
PU/PTB-18050H/20
180mm Polyurethane Steer Wheel with 20mm Ball Bearing
PJPU/WPR9680
96mm x 80mm Flat Polyurethane Pallet jack Roller

5. Pallet jack no. 42 (B/C: DOH717599)

Replace with:

PU/PTB-20020H/20

200mm Polyurethane Steer Wheel with 20mm Ball Bearing

PU/PJ/WPR6080

Polyurethane Pallet roller 60mm × 80mm

6. Pallet jack no. 37 (B/C: AB030837)

Replace with:

PU/PTB-18050H/20

80mm Polyurethane Steer Wheel 20mm Ball Bearing

PU/PTB-08070/20

80mm × 70mm Polyurethane Pallet Roller with 20mm Ball

7. Pallet jack no. 35 (B/C: AB030846)

Replace with:

PU/PTB-18050H/20

180mm Polyurethane Steer Wheel with 20mm Ball Bearing

PU/PTB-08070/20

80mm × 70mm Polyurethane Pallet Roller with 20mm Ball Bearing

8. Pallet jack no. 30 (B/C: DOH717598)

Replace with:

PU/PTB-18050H/20

180mm Polyurethane Steer Wheel with 20mm Ball Bearing

PU/PJ/WPR6080

Polyurethane Pallet Roller 60mm × 80mm

9. Pallet jack no.34 (B/C: AA700834)

Replace with:

PU/PTB-20050H/20

200mm Polyurethane Steer Wheel with 20m Ball Bearing

PU/PJ/WPR6080

Polyurethane Pallet Roller 60mm × 80mm

10. Pallet jack no. (B/C: AA7006460)

Replace with:

PU/PTB-20050H/20

200mm Polyurethane Steer Wheel with 20m Ball Bearing

PU/PJ/WPR6080

Polyurethane Pallet Roller 60mm × 80mm

11. Pallet jackno.39 (B/C:AA700651)

Replace with:

PU/PTB-20050H/20

200mm Polyurethane Steer Wheel with 20mm Ball Bearing

PJPU/WPR9680

96mm Flat Polyurethane Pallet Jack Roller

12. Pallet jack no. 38 (B/C: AA700643)

Replace with:

PU/PTB-20050H/20

200mm Polyurethane Steer Wheel with 20m Ball Bearing

PU/PPJ/WPR6080

• KINDLY RETURN **ALL DOCUMENTATION** WHEN REPLYING

13. Pallet jack no. 20 (B/C: AB030845)

Replace with:

PU/PTB-18050H/20

180mm Polyurethane Steer Wheel with 20mm Ball Bearing

PU/PJ/WPR8070

80mm x 70mm Polyurethane Pallet Jack Roller Wheel

14. Pallet jack no. 33 (B/C: AB030838)

Replace with:

PU/PTB-18050H/20

180mm Polyurethane Steer Wheel with 20mm Ball Bearing

PU/PJ/WPR8070

80mm x 70mm Polyurethane Pallet Jack Roller Wheel

15. Pallet jack no. 7 (B/C: DOH717591)

Replace with:

PU/PTB-18050H/20

180mm Polyurethane Steer Wheel with 20mm Ball Bearing

PU/PJ/WPR8070

80mm x 70mm Polyurethane Pallet Jack Roller Wheel

16. Pallet jack no. 44 (B/C: AA700636)

Replace with:

PU/PTB-18050H/20

180mm Polyurethane Steer Wheel with 20mm Ball Bearing

PJPU/WPR9680

96mm Flat Polyurethane Pallet Jack Roller

17. Pallet jack no 36 (B/C: AB030836)

Replace with:

PU/PTB-18050H/20

180mm Polyurethane Steer Wheel with 20mm Ball Bearing

PU/PTB-08070/20

80mm x 70mm Polyurethane Pallet Roller with 20mm Ball Bearing

The awarded Contractor/Supplier of service is required report to the following respective Facility management officials once the above required repairs have been concluded and that the work is done accordance of the above.

- Mr C Mtambo
- Mr S Naicker

Signed: 
 Assistant Director
 Support Services

Date 14 / 7 / 22

Signed: 
 SCM Supervisor
 Demand Management

Date 14 / 7 / 22

-
- KINDLY RETURN ALL DOCUMENTATION WHEN REPLYING