Quotation Advert

Opening Date:

25/01/2023

Closing Date:

06/02/2023

Closing Time:

11:00

INSTITUTION DETAILS

Institution Name:

Othobothini CHC

Province:

KwaZulu-Natal

Department of entity:

Department of Health

Division or section:

Central Supply Chain Management

Place where goods/ service is required:

Date Submitted:

25/01/2023

ITEM CATEGORY AND DETAILS

Quotation number:

ZNQ: OTH/170/2022/2023

Item Category:

Services

Item Description:

Repair of the following Items as per attached list at Ophondweni Clinic and

Othobothini CHC D850 Road next to Msiyane High School Jozini 3969

Nondabuya Clinic

Quantity (if supplies):

COMPULSORY BRIEFING SESSION / SITE VISIT

Select Type:

Compulsory Site Meeting

Date:

31/01/2023

Time:

10:00AM

Venue:

Ophondweni Clinic (Starting Point)

QUOTES CAN BE COLLECTED FROM:

OTHOBOTHINI CHC, SCM OFFICE/ DOWNLOAD FROM

THE DEPARTMENT WEBSITE

QUOTES SHOULD BE DELIVERED TO:

OTHOBOTHINI CHC, QUOTATION BOX/EMAIL TO

othobothini.quotations@gmail.com

ENQUIRIES REGARDING ADVERT MAY BE DIRECTED TO:

Name:

MR Z.V MTHIYANE

Email:

Othobothini.quotations@gmail.com

Contact number: 035 572 9002

Finance Manager Name:

Miss NP DUBE Finance Manager Signature



DIRECTORATE:

PHYSICAL ADDREESS: Othobothini CHC, D850 Road, Msiyane Reserve next to Msiyane High School POSTAL ADDRES : Private Bag X12, Jozini, 3969

TEL

: 035 572 9002 /035 512 9013

EMAIL ADDRESS

:Khethokwakhe.Dlamuka@kznhealth.gov.za

Ophondweni clinic

List items for repair

1. Repair wooden double door at OPD and emergency door

- 2. Repair 10 square metre damaged ceiling at (CCMDD room, room 05, passage to maternity, nurses home, prof nurses)
- 3. Repair 5 toilets
- 4. Repair damaged floor to Park home
- 5. Repair ramp at main exit door
- 6. Repair leaking tap in staff kitchen
- 7. Replace broken glass door
- 8. Repair kitchen cupboard, maternity room5, nurses home, prof nurses and enrolled nurses house
- 9. Repair 20 outside light at the entrance ,nurses home and clinic
- 10. Repair steel windows 08 (window stay and window handles)

Compiled by JN Gumede



DIRECTORATE:

PHYSICAL ADDREESS: Othobothini CHC , D850 Road, Msiyane Reserve next to Msiyane High School

POSTAL ADDRES : Privat TEL : 035 5

: Private Bag X12 ,Jozini ,3969 : 035 572 9002 /035 512 9013

EMAIL ADDRESS

:Khethokwakhe.Dlamuka@kznhealth.gov.za

Nondabuya clinic

- 1. Repair 06 toilets
- 2. Repair 15 steel window (window stay and handles)
- 3. Repair of main entrance wooden door
- 4. Repair of door 08 mortise lock
- 5. Repair glass doors in nurses home : room 01 and 02
- 6. Repair three stoves
- 7. Repair 10 square metres sinking ceiling in treatment room and sluice room
- 8 Repair of roof of the waste cage
- 9. Repair of cupboard in room 02 disaster cupboard
- 10. Repair 16 outside light

Compiled by : J N Gumede RP



DIRECTORATE:

отновотнімі снс

SYSTEMS

www.kznhealth.gov.za

Requirements for repairing the following list items

- CIDB GRADE GB/ME AND SO
- CERTIFICATE OF GOOD STANDING
- BBBEE CERTIFICATE
- TRADE TEST CERTIFICATE