

Quotation Advert

Opening Date:

02/11/2023

Closing Date:

13/11/2023

Closing Time:

11:00

INSTITUTION DETAILS

Institution Name:

Provnicial Pharmaceutical Supply Depot

Province:

KwaZulu-Natal

Department of entity:

Department of Health

Division or section:

Central Supply Chain Management

Place where goods/

service is required:

Provincial Pharmaceutical Supply Depot

Date Submitted:

02/11/2023

ITEM CATEGORY AND DETAILS

Quotation number:

PSD/ZNQ0063/23-24

Item Category:

Services

Item Description:

After Services Repairs To Toilet Systems At PPSD

Quantity (if supplies):

10

COMPULSORY BRIEFING SESSION / SITE VISIT

Select Type:

Compulsory Site Meeting

Date:

08/11/2023

Time:

12:00

Venue:

Provincial Pharmaceutical Supply Depot

QUOTES CAN BE COLLECTED FROM:

PPSD / KZN HEALTH WEBSITE

QUOTES SHOULD BE DELIVERED TO:

PPSD Tender Box / Email:

ppsd.acquisitions@kznhealth.gov.za

ENQUIRIES REGARDING ADVERT MAY BE DIRECTED TO:

Name:

Rashida Pillay / Neren Inderpershad

Email: rashida.pillay@kznhealth.gov.za or Contact number: 031-4698874

Finance Manager Name:

Mr S Naicker Assistant Director S/S Signature

1 Higginson Highway, Mobeni, 4052 Private Bag X03, Mobeni, 4060 Tel: 031 4698300 Fax: 031 4629158 Email: Sagathevan.naicker@kznhealth.gov.za www.kznhealth.gov.za DIRECTORATE:

PHARMACEUTICAL SERVICES

SCOPE OF WORK:

SERVICE AND MAINTENANCE TO ABOLUTION FACILITY AT PPSD

Allow for service and replacement of the following at the following locations:

Toilets (Room A9), (Room A21), (Room Q11)

- Diaphragm
- Ball valve washer
- Flush trumpets
- Lubrication of flush handle and housing
- Allow for service and replacement of the following at the following locations:
 - Male Toilet Ground Floor (Room A8), Replace complete flushing mechanism to match the existing or similar to the existing with press button.
 - Male Toilet- First floor (Room A20), Replace complete Ball Valve flushing mechanism to match the existing or similar to the existing with front flush handle.
 - Supply and install new cartridge on a press button tap sink at the following location:
 Female Toilet (Room A9).
 - Replacement of pan seal at the following locations:
 Receipts Section (Room 21 &23)
 Ex Manufacturing Laboratory Male toilets (Cubicle 1&2)
- Replacement of toilet seat covers(SABS approved) at the following locations:
 - Ground floor male toilet (Room A8)
 - First floor QC Laboratory toilet (Room Q11)
 - Ex Manufacturing Laboratory Male toilets (Cubicle 2)
- Replacement of Indicator Bolt at the following locations: Room R21 x1, Room R 22 x1, Room R23 x2, Manlab x4, Room A21 x 1, Room A20x1, Room Q11 x1
 Total Quantity eleven (11)

Note:

The awarded Contractor/ Supplier of service is required to report to the following respective Facility management officials once the above required repairs have been concluded and that the work is done in accordance of the above.

Date: 2023/11/01

Signed etchn

Date: 2023/11/01

SCM Supervisor

Demand Management

