
AVERAGE DEPARTMENT CONDITION



LEGEND: MAIN CLINIC BUILDING SECURITY GATEHOUSE STAFF RESIDENCE STAFF HOUSE PATIENTS TOILETS CARPORT B001 B002 B003 B004 B005 B006

